

CERTIFICATE OF TESTING




Allan Marketing Group

42 Clements Avenue

Bundoora VIC 3083



Customer :	HESNZ	Test Report # :	091014130
Address :	Auckland New Zealand	Test Type :	Break Test
Customer PO # :		Peak Load :	6912.684 kgf
Order # :		Peak Elongation :	61.451 mm
Item Serial # :		Test Duration :	0:2:32.3 (H:M:S)
Test Date :	09/10/14	Test Standard :	NZS5467- G70 Traylor Chain
Test Time :	09:48:38	W.L.L. :	2500.000 kgf
Description :	G70 Trailer Chain 8mm LC2.5T	Comments :	
Customer Notes :	Markings G70 AMG3		



123
456
789*/****

Acceptable
 Not Acceptable

Test Operator : _____